



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Dual instruction.

Stbd wheel tire burst after life of 21.30 hours.

NATURE OF ACCIDENT:

Stbd tire punctured by piece of wire while taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

Tire B

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

(Nil)