

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE MA.	DATE 3-10-43	TIME 1830
A/C TYPE HARVARD II		NO. 2564	CRASH CAT. "D"1/72	H.Q. FILE 1100-25-64
		S.E. x	M.E.	DAY x
				NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Hattrem, P.	LT	1195	FI	Uninj.	NO.	DATE
Olufsen, E.B.	LAC	2148	PP	Uninj.		
<b>FIRE FAILURE</b>					D 14 (REVISED)	
					No. 10	CHECKED <input checked="" type="checkbox"/>
					#28	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
Wapp S3HI	4284/8425 Nil	-	-	SOLO	DUAL	SOLO	DUAL
				230	-	1220	37

ACCIDENT CLASSIFICATION

COMMAND  
 MONTH  
 STAGE OF FLIGHT

7  
 4  
 2  
 1  
 7  
 4  
 2  
 1  
 FORCED LANDING  
 TAXIING  
 LANDING  
 TAKE-OFF  
 FLIGHT  
 STATRY  
 FATAL  
 INJ  
 3RD  
 5  
 INJURY  
 2  
 1

PURPOSE OF FLIGHT:

Z.Z. Approaches.

NATURE OF ACCIDENT:

Tail wheel tire burst on landing.

TECHNICAL OFFICER'S REPORT:

Tail wheel burst after life of 69.30 hours.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

200/000

CLASSIFICATION:

15. Fire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil