



PURPOSE OF FLIGHT:

(3019) 6,7,8,9,20.  
(BW200) 6,7,8,16,20.

TECHNICAL OFFICER'S REPORT:

NATURE OF ACCIDENT:

A/C 3019 after completing cockpit check, pulled out to taxi up to take-off post. Failed to see a/c BW200 which was parked on opposite side of taxi strip and collided with same.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

*None*  
*TCA/10:1* ✓  
*TCA/10*

CLASSIFICATION:

3. Hitting other a, c.

9

SECONDARY OR CONTRIBUTORY FACTORS:

24. Carelessness.

ACTION TAKEN:

Grounded for one month and placed on charge for negligently damaging one of his Majesty's A/C.  
Log book endorsed.