

CASPIR Aircraft Accident Cards

Serial: AJ928

Title: North American Harvard Mk. II / 2 serial:AJ928 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-October-14. Harvard II s/n AJ928. This accident involved 2 people. Ardern FW, Macmurchie I

Keywords: RAFHarvard II,AJ928,41 SFTS,41 Service Flying Training School,R2
Ralph,1943-October-14,Ardern,MacmurchieRCAF L20

Created: 1943-10-14

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ928>

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 41 S.F.T.S. Weyburn	COM. 2	PLACE R2 Ralph	DATE 14-10-43	TIME 1710
A/C TYPE HARVARD II		NO. AJ928	CRASH CAT. "C"3	H.Q. FILE 1300-AJ928
PERSONNEL		RANK	NUMBER	DUTY
Ardern, F.W.		SGT	1519713	FI
MacMurchie, I.		LAC	1050405	PP
INJURIES		SIGNAL		
Uninj		NO.	DATE	
Uninj.		A.185	15-10	
		D 14 (REVISED)		
		NO.	CHECKED	
		5	<input checked="" type="checkbox"/>	
		#67		

COMMAND

MONTH

STAGE OF FLIGHT

7
4
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ
INJURY
3RD
5
M
N

TYPE OF A/C

TYPE OF UNIT

CATEGORY

ENGINE	ENGINE NUMBER(S)	HOURS FLOWN BY PILOTS					
Wasp S3HI	7903/4083 Nil	INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
		42	25	92	98	135	155
		8	5	26	44	61	79

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF M N

PURPOSE OF FLIGHT:

Precautionary landing approaches.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Approached at too low speed, where-
upon instructor took over but was un-
able to prevent wheels touching. A/C
ground looped and port oleo leg collapsed.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LH/P 342/2/USH ✓

CLASSIFICATION:

~~40. Heavy landing - flying into ground.~~

HEAVY.

4

SECONDARY OR CONTRIBUTORY FACTORS:

~~38. Ground loop~~

ACTION TAKEN:

Nil