

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE Holsom RI	DATE 17-10-43		TIME 1525				
			H.Q. FILE 1300-FE926						
A/C TYPE HARVARD IIB		NO. FE926	CRASH CAT. "B"	S.E. X	M.E.	DAY X	NIGHT		
PERSONNEL Whelan, D.		RANK LAC	NUMBER 1520721	DUTY PP	INJURIES Uninj.		SIGNAL		
							NO. A.785	DATE 19-10	
							D 14 (REVISED)		
							NO. 10/37	CHECKED 11	
							#85		
ENGINE R.1340 AN-1		ENGINE NUMBER(S) 42-9510/21849		HOURS FLOWN BY PILOTS					
		Nil		INST.	NIGHT	ON TYPE		TOTAL	
						SOLO	DUAL	SOLO	DUAL
				-	-	2	11	82	128

TYPE OF A/C
TYPE OF UNIT
CATEGORY

COMMAND
MONTH
STAGE OF FLIGHT

- 7
- 4
- 2
- 1
- 7
- 4
- 2
- 1
- FORCED LANDING
- TAXIING
- LANDING
- TAKE-OFF
- FLIGHT
- STAT RV
- FATAL
- INJ
- INJURY
- 3RD
- 5
- RAF
- M

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Local solo exercises.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

A/c was allowed to swing near end of landing run, and swung to right off runway. Port tire burst, port wheel dug into soft ground and a/c overturned.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~61. Swinging on landing.~~

SWUNG.

2

SECONDARY OR CONTRIBUTORY FACTORS:

~~37. Overturning~~

~~43. Tire trouble.~~

ACTION TAKEN: