

ACCIDENT CLASSIFICATION

UNIT	34 S.F.T.S. Medicine Hat		COM.	4	PLACE	M.A.		DATE	23-10-43		TIME	2315	COMMAND	
	A/C TYPE	HARVARD II		No.	AJ961		CRASH CAT.	"C"2		S.E.	X	M.E.		DAY
PERSONNEL			RANK	NUMBER	DUTY	INJURIES		SIGNAL		MONTH		STAGE OF FLIGHT		
Tompkins, W.C.			LAC	1583226	PP	Uninj.		No.	DATE	A.822 24-10				
								D 14 (REVISED)						
								No.	CHECKED	59				
										#115				
ENGINE		ENGINE NUMBER (S)			HOURS FLOWN BY PILOTS									
Wasp S3H1		8148/4167 Nil			INST.	NIGHT	ON TYPE		TOTAL					
							SOLO	DUAL	SOLO	DUAL				
					28	13	32	49	64	91				

ACCIDENT CLASSIFICATION

TYPE OF A/C
TYPE OF UNIT
CATEGORY

7
4
2
1
7
4
2
1
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
3RD
5
RAF
M N

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

N/F circuits and landings.

Nil

NATURE OF ACCIDENT:

Ground looped after bounce on landing at night.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LH/PSHL

CLASSIFICATION:

~~40. Heavy landing - flying into ground.~~

HEAVY.

A

SECONDARY OR CONTRIBUTORY FACTORS:

~~38. Ground loop.~~

ACTION TAKEN:

Nil