

ACCIDENT CLASSIFICATION

UNIT 34 O.T.U. Pennfield Ridge E	COM. E	PLACE M.A.	DATE 27-10-48	TIME 0130 GMT
A/C TYPE VENTURA II	NO. AJ448	CRASH CAT. "B"	H.Q. FILE 1300-AJ448	
			S.E. x	M.E. x
			DAY	NIGHT x

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
Squance, J.H.	GB P/O	153549	PP	Uninj.	NO. DATE
Anderson, H.L.	SGT	R197565	WRG	Uninj.	A.655 27-10
					D 14 (REVISED)
					NO. CHECKED
					2 <input checked="" type="checkbox"/>
					#5

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Pratt & Whitney	BU95419/113702 Nil						
	BU95394/113650 Nil	38	27	12	11	107	155

ACCIDENT CLASSIFICATION

COMMAND

MONTH


STAGE OF FLIGHT

- FORCED LANDING
- TAXIING
- LANDING
- TAKE-OFF
- FLIGHT
- STAT'RY
- FATAL
- INJ. 1st
- INJ. 2nd
- INJ. 3rd
- INJ. 4th
- INJ. 5th

TYPE OF A/C

TYPE OF UNIT

CATEGORY



PURPOSE OF FLIGHT:

Training flight.

NATURE OF ACCIDENT:

A/C AJ448 was parked at the taxiing post and was run into by a/c AE703. Tail light of AJ448 was faulty and was not on at time of the accident.

TECHNICAL OFFICER'S REPORT:

Nil

11041
TCA/PSI
TCA/RA

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

3. Hitting other a/c. 9

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Pilot of AE703 - Log book endorsed.