

ACCIDENT CLASSIFICATION

UNIT	123 Sqdn	COM.	E	PLACE	Debert aerodrome		DATE	15-10-43	1120						
	A/C TYPE		HURRICANE XII HUDSON		No.	5726 BW775	CRASH CAT.	"C"1 "C"	S.E.	X	M.E.		DAY	X	NIGHT
PERSONNEL		RANK	F/O	NUMBER	J22381	DUTY	P	INJURIES		Uninj.		SIGNAL			
Elfner, P.J.								No.	A.190	DATE	15-10	D 14 (REVISED)			
								No.	2	CHECKED	<input checked="" type="checkbox"/>	#10			
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS											
Packard Merlin XXIX		19560/A-3065 Nil		ON TYPE				TOTAL							
				INST.	NIGHT	SOLO	DUAL	SOLO	DUAL	SOLO	DUAL				
				52	23	23	-	380	105	455					

ACCIDENT CLASSIFICATION

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATIONARY
FATAL
INJURY
3RD
M 2

PURPOSE OF FLIGHT:

N.A.

TECHNICAL OFFICER'S REPORT:

Nil

MA/10
10/11/54

NATURE OF ACCIDENT:

While taxiing to downwind end of runway 16, pilot passed at right angles behind a Hudson which was doing engine run-up. Resulting slipstream caught Hurricane broadside and caused it to weathercock into another Hudson which was parked next to the one doing run-up. Pilot was unable to prevent collision despite violent use of brakes.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~57. Miscellaneous.~~

OTHERS.

R //

SECONDARY OR CONTRIBUTORY FACTORS:

~~3. Hitting other a/c.~~

ACTION TAKEN:

Nil