

ACCIDENT CLASSIFICATION

UNIT 10 E.F.T.S. Pendleton	COM. 3	PLACE M.A.	DATE 1840-43 1930	TIME
A/C TYPE TIGER MOTH 82C TIGER MOTH 82C		No. 8955-13 3955	CRASH CAT. "C"1 "C"2	H.Q. FILE 1100-89-55
		S.E. X	M.E.	DAY
				NIGHT X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Johnston, G.S.	WO2	R107465	FI	Uninj.	No.	DATE
Edge, H.L.	SGT	R225246	PP	Uninj.	A.1398	19-10
York, C.	WO2	R137158	FI	Uninj.	D 14 (REVISED)	
Hurdmar, H.G.	LAC	R207266	FP	Uninj.	No.	CHECKED
					5	<input checked="" type="checkbox"/>
					#32	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
Gipsy Major I	1429/89271 Nil			SOLO	DUAL	SOLO	DUAL
	12930/89399 Nil						
		68	114	790	80	1103	156
		7	3	20	31	20	31
	55	115	635	20	910	141	
	8	31	23	32	23	32	

TYPE OF A/C	TYPE OF UNIT	CATEGORY	ACCIDENT CLASSIFICATION		COMMAND	MONTH	STAGE OF FLIGHT		
			FORCED LANDING	TAXIING				LANDING	TAKE OFF

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

PURPOSE OF FLIGHT:

Practicing night circuits and landings.

TECHNICAL OFFICER'S REPORT:

Nil

TCA / 1107
TCA / X 7

NATURE OF ACCIDENT:

A/C 8955 taxied into a/c 3955 after receiving green light which pilot in a/c 8955 thought was permission for him to take-off.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~3. Hitting other a/c.~~

COLLISIONS.

Q

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness.~~

ACTION TAKEN:

Log book endorsed.