

ACCIDENT CLASSIFICATION

TYPE OF A/C	UNIT	34 S.F.T.S.	COM.	4	PLACE	M.A.	DATE	3-11-43	TIME	0145	COMMAND					
		Medicine Hat					H.O. FILE	1100-20-90								
TYPE OF UNIT	A/C TYPE	HARVARD II			NO.	2690	CRASH CAT.	"C"7	S.E.	X	M.E.	DAY	NIGHT	X	MONTH	
	PERSONNEL	Punter, E.			RANK	LAC	NUMBER	1802228	DUTY	PF	INJURIES		Uninj.			SIGNAL
CATEGORY	ENGINE		ENGINE NUMBER (S)			HOURS FLOWN BY PILOTS				ON TYPE		TOTAL		STAGE OF FLIGHT		
	Wasp S3HI		26229, 12159 Nil			INST.	NIGHT	SOLO		DUAL		SOLO			DUAL	
						30	25	30		70		40			100	

ACCIDENT CLASSIFICATION

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
 1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
 FORCED LANDING
 TAXIING
 LANDING
 TAKE-OFF
 FLIGHT
 STATIONARY
 FATAL
 INJ.
 3RD
 INJURY
 5
 RATE
 M 2

PURPOSE OF FLIGHT:
N/F cross-country.

TECHNICAL OFFICER'S REPORT:
Nil

NATURE OF ACCIDENT:
Landed with u/c retracted.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:
FINDINGS: SUMMARY No.

LUC / POND / LIDE

CLASSIFICATION:
~~34. Wheels up landing.~~ 7
7. Other

SECONDARY OR CONTRIBUTORY FACTORS:
~~32. Pilot error.~~
32 1/2 hr Drill - 32
in air

ACTION TAKEN:
Further investigation.