

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat		COM. 4	PLACE Holson Rd			DATE 6-11-43	TIME 1600	
A/C TYPE HARVARD II		NO. 2613	CRASH CAT. "D"1/72	S.E. x	M.E.	DAY x	NIGHT	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL	
Crawford, J.L.		P/O	55218	FI	Uninj.		No. DATE	
Sharpe, R.D.		LAC	R209421	PF	Uninj.		No. DATE	
<p style="font-size: 2em; opacity: 0.5;">TAIL FAILURE</p>						D 14 (REVISED)		
						No. 14	CHECKED <input checked="" type="checkbox"/>	
						44		
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
asp S3HI	4070/7890 Nil		INST.	NIGHT	ON TYPE		TOTAL	
			-	-	SOLO	DUAL	SOLO	DUAL
			-	-	250	100	300	175
			-	-	-	5	35	34

ACCIDENT CLASSIFICATION

TYPE OF A/C  
TYPE OF UNIT  
CATEGORY

COMMAND  
MONTH  
STAGE OF FLIGHT

FORCED LANDING  
TAXYING  
LANDING  
TAKEOFF  
FLIGHT  
STATRY  
FATAL  
INJ.  
INJURY

RAF M 2

PURPOSE OF FLIGHT:

Circuits and landings.

TECHNICAL OFFICER'S REPORT:

Burst tail wheel tire after life of 83.15 hours.

NATURE OF ACCIDENT:

Burst tailwheel tire while taxiing off landing path.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

*TU/UT-1*

CLASSIFICATION:

43. Tire trouble.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil