

## CASPIR Aircraft Accident Cards

---

**Serial:** FE929

**Title:** North American Harvard Mk. IIB serial:FE929 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-November-08. Harvard IIB s/n FE929. This accident involved 2 people. James PH, Thompson AG

**Keywords:** RAFHarvard IIB,FE929,34 SFTS,34 Service Flying Training School,Holsom R1,1943-November-08,James,ThompsonRCAF L20

**Created:** 1943-11-08

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE929>

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

TYPE OF A/C	UNIT 34 S.F.T.S.	COM. 4	PLACE Holsom R.1	DATE 8-11-43	TIME 1100				
	A/C TYPE Medicine Hat HARVARD II B		No. FE929	H.Q. FILE 1300-FE929					
			CRASH CAT. "E"	S.E. X	M.E. 				
				DAY X	NIGHT 				
TYPE OF UNIT	PERSONNEL		RANK	NUMBER	DUTY	INJURIES	SIGNAL		
	James, P.H.		P/O	152898	F.I.	Uninj.	No.	DATE	
	Thompson, A.G.		LAC	1624563	PP	Uninj.			
	<i>John Fullerton</i>						D 14 (REVISED)		
							No.	CHECKED	
							11/16	W	
							#56		
CATEGORY	ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				STAGE OF FLIGHT	
	Wasp R1340	42/ 9513/21852		INST.	NIGHT	ON TYPE		TOTAL	
						SOLO	DUAL	SOLO	DUAL
				-	-	200	100	249	151
				-	-		4	40	30

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING

TAXIING

LANDING

TAKEOFF

FLIGHT

STATRY

FATAL

INJURY

3RD

M X

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

RAF M X

