



PURPOSE OF FLIGHT:

Circuits & Landings.

TECHNICAL OFFICER'S REPORT:

NIL.

NATURE OF ACCIDENT:

Pupil carrying out a landing failed to correct swing and a/c groundlooped.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

43/002

CLASSIFICATION:

38. Ground loop.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL.