

CASPIR Aircraft Accident Cards

Serial: 2716

Title: North American Harvard Mk.II serial:2716 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-November-20. Harvard II s/n 2716. This accident involved 1 person. O'Hara P

Keywords: RAFHarvard II,2716,34 SFTS,34 Service Flying Training School,Aerodrome,1943-November-20,O'HaraRCAF L20

Created: 1943-11-20

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2716>

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.	DATE 20-11-43 TIME 0035
A/C TYPE HARVARD II	No. 2716	CRASH CAT "D"1	H.O. FILE 1100-27-16
		S.E. x	M.E. DAY x

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
O'Hara, E.	LAC	1474480	FP	Uninj.	No. A.962	DATE 20-11
					D 14 (REVISED)	
					No. 35	CHECKED <input checked="" type="checkbox"/>
					#81	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Wasp S3HI	4571/9012 Nil	18	9	16	28	60	100

ACCIDENT CLASSIFICATION

TYPE OF A/C
TYPE OF UNIT
CATEGORY
COMMAND
MONTH
STAGE OF FLIGHT

7
4
2
1
7
4
2
1
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATARY
FATAL
INJ.
3RD
INJURY
5
RAF
M

PURPOSE OF FLIGHT:

Night flying landings.

NATURE OF ACCIDENT:

Ground looped on landing at night.

TECHNICAL OFFICER'S REPORT:

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LS/PSS ✓

CLASSIFICATION:

~~38. Ground loop.~~

2. *Swung* 2

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error.~~

ACTION TAKEN:

Nil