

CASPIR Aircraft Accident Cards

Serial: 2792

Title: North American Harvard Mk.II serial:2792 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-November-22. Harvard II s/n 2792. This accident involved 2 people. Deblommaert AH, Lorrimore JR

Keywords: RAFHarvard II,2792,34 SFTS,34 Service Flying Training School,Aerodrome,1943-November-22,Deblommaert,LorrimoreRCAF L20

Created: 1943-11-22

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2792>

PURPOSE OF FLIGHT:

Adv. Formation.

NATURE OF ACCIDENT:

Stbd tire burst on landing.

TECHNICAL OFFICER'S REPORT:

Stbd tire burst after life of 415.15 hours.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

200/672

CLASSIFICATION:

43. Tire trouble.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil