



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Local Dual

Tail wheel tyre burst after life of 168.40 Hours.

NATURE OF ACCIDENT:

Tail wheel tyre burst whilst taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

*TWC/07007*

CLASSIFICATION:

43. Tire trouble.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL.