

## CASPIR Aircraft Accident Cards

---

**Serial:** FP933

**Title:** Avro Anson Mk. II serial:FP933 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1943-November-18. Anson II s/n FP933. This accident involved 2 people. Bond KG, Davies DO

**Keywords:** RCAFAnson II,FP933,15 SFTS,15 Service Flying Training School,Aerodrome,1943-November-18,Bond,DaviesRCAF L20

**Created:** 1943-11-18

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP933>

ACCIDENT CLASSIFICATION

UNIT 15 S.F.T.S. Clareholm, Alta.	COM. 4	PLACE M.A.	DATE 18-11-43	TIME 0850
A/C TYPE ANSON II	No. FP 933	CRASH CAT. "C" 10	H.Q. FILE 1300-FP933	S.E. X
			M.E. X	DAY X
				NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
Davies, D.O.	F/O	J12241	P	Uninj.	No. A97 DATE 18-11
Bond, K.G.	NZ LAC	4215083	PP	Uninj.	D 14 (REVISED)
					No. 4 CHECKED <input checked="" type="checkbox"/>
					#51

MONTH

STAGE OF FLIGHT

ENGINE	ENGINE NUMBER(S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
Jacobs L6MB	26733/9987	Nil		SOLO	DUAL	SOLO	DUAL
	25448/9818	Nil					
		69	112	682	30	985	150
		7	3	-	2	26	37

FATAL

ACCIDENT CLASSIFICATION

4  
2  
1  
7  
4  
2  
1  
4  
1  
FORCED LANDING  
TAXIING  
LANDING  
TAKE OFF  
FLIGHT  
STATRY  
FATAL  
INJ  
INJURY  
3RD  
S  
M 2

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

PURPOSE OF FLIGHT:

Dual seq. 6,7,8, and 21A.

TECHNICAL OFFICER'S REPORT:

Nil

*TCO/UBH*

NATURE OF ACCIDENT:

A/C while taxiing, started a gentle groundloop to stbd. Stbd wing collided with timekeepers hut.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~46. Brake failure.~~

*9*

*9. Collision*

SECONDARY OR CONTRIBUTORY FACTORS:

~~38. Ground loop.~~

~~41. Hitting obstructions,~~

*36 Brake Failure 36*

ACTION TAKEN:

Nil