

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

TYPE OF A/C	UNIT 33 S F.T.S. Carberry	COM. 2	PLACE RI Petrel	DATE 18-11-43	TIME 1230		
	A/C TYPE ANSON II	No. 11199	CRASH CAT. "D"2	H.Q. FILE 1100-111-99	S.E.	M.E. X	NIGHT X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Atkins, J.A.C.	F/O	151503	FI	Uninj.	NO.	DATE
Sheppard, O.E.	LAC	1652986	PP	Uninj.	A.90	19-11
					D 14 (REVISED)	
					NO. 5	CHECKED <input checked="" type="checkbox"/>
					#53	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
Jacobs L6MB	10393/25639	Nil		SOLO	DUAL	SOLO	DUAL
	25108/9478	Nil	50	67	386	11	520

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61

COMMAND
MONTH
STAGE OF FLIGHT
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
INJURY
3RD
S
RAF
M 2

PURPOSE OF FLIGHT:

Formation flying exercise.

TECHNICAL OFFICER'S REPORT:

Nil

7/6/57

NATURE OF ACCIDENT:

Instructor taxied too close to stake striking same with tail as he joined the rank,

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~2. Hitting obstruction.~~

9. Collision

9

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Summary of evidence being taken.