


ACCIDENT CLASSIFICATION

UNIT 4 S.F.T.S. Saskatoon		COM. 2	PLACE M.A.		DATE 12-11-43	TIME 1400			
A/C TYPE Crane I		NO. 7814		CRASH CAT. E2	S.E.	M.E. X	DAY X	NIGHT	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
Heady, J.		LAC	GB1615776	PP	Uninj.		NO. D139	DATE 13-11	
		D 14 (REVISED)						NO. #5	CHECKED <input checked="" type="checkbox"/>
								#6	
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Jacobs		P.21890/4791 Nil.		INST.	NIGHT	ON TYPE		TOTAL	
LAMB		S.22564/8131 "				SOLO	DUAL	SOLO	DUAL
				19	11	13	36	37	92

COMMAND

MONTH

STAGE OF FLIGHT

- FORCED LANDING
- TAXIING
- LANDING
- TAKE-OFF
- FLIGHT
- STATIONARY
- FATAL
- INJURY
- 3rd
- 5

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Solo practice circuits & Landings

TECHNICAL OFFICER'S REPORT:

NIL.

CM/XGM

NATURE OF ACCIDENT:

Stbd. wheel struck a large stone on take off causing it to fly up and strike the trailing edge of the flap and the under side of the stbd. tail plane.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

57. Miscellaneous.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL.