

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 6 E.F.T.S.	COM. 2	PLACE M.A.	DATE 15-11-73 TIME 1830
Prince Albert			H.Q. FILE 1100-50-74
A/C TYPE TIGER MOTH TIGER MOTH	NO. 5074	CRASH CAT. C	S.E. X M.E. DAY NIGHT
	5944 -D	C	X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
GOIN, J.W.	WO2	R113186	FI	Nil	NO. A942	DATE 16-11
Behan, J.K.	LAC	R251889	PP	Nil	D 14 (REVISED)	NO. 3 CHECKED <input checked="" type="checkbox"/>
Jardine, D.E.	LACU	208519	PP	Nil		
					#21	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS						
Gypsy Major	7558/85450 7079/82969	Nil	INST.	NIGHT	ON TYPE		TOTAL	
					SOLO	DUAL	SOLO	DUAL
			55	94	865	81	943	140
			3	-	9	17	9	17
			1	-	19	19	19	19

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

7
4
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKE OFF
FLIGHT
STATRY
FATAL
INJ.
3RD
INJURY
S
M
N

PURPOSE OF FLIGHT:

5944 solo practice.
5074 Dual instruction.

TECHNICAL OFFICER'S REPORT: *M...*

Nil *TCA/...*
TCA/...

NATURE OF ACCIDENT:

While taxiing to leeward end of field a/c 5944 occupied by LAC Jardine taxied into a/c 5074 which was in parked position prior to take-off. Pupil in a/c 5944 states he did not observe parked a/c until he taxied into it.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~3. Hitting other a/c.~~ 9
9. Collision

(c) Student (Jardine) has been progress tested and his flying training discontinued. He was found to lack airmanship and did not possess sufficient ability to make a safe pilot.

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error.~~

ACTION TAKEN:

Nil