



PURPOSE OF FLIGHT:

Circuits and Landings.

TECHNICAL OFFICER'S REPORT:

Tailwheel tyre burst after life of 196 hours.

NATURE OF ACCIDENT:

Tail wheel tyre burst whilst taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL.