



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Local Dual exercises

Tail wheel tyre burst after life of 168:35 hours

NATURE OF ACCIDENT:

Tail wheel tyre burst whilst taxiing

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

NIL

ACTION TAKEN:

NIL.