

CASPIR Aircraft Accident Cards

Serial: FE640

Title: North American Harvard Mk. IIB serial:FE640 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-December-19. Harvard II s/n FE640. This accident involved 1 person. Larkins J

Keywords: RAFHarvard II,FE640,41 SFTS,41 Service Flying Training School,Aerodrome,1943-December-19,LarkinsRCAF L20

Created: 1943-12-19

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE640>

ACCIDENT CLASSIFICATION

UNIT 41 S.F.T.S. Weyburn		COM. 2	PLACE M.A.		DATE 19-12-43	TIME 1430	
A/C TYPE HARVARD II		No. FE 640	CRASH CAT. "D"		S.E. X	M.E.	DAY X
PERSONNEL Larkins, J		RANK LAC	NUMBER 1670377	DUTY PP	INJURIES Uninj.		SIGNAL
							No. DATE A10 19-12
							D 14 (REVISED)
							No. CHECKED 5 <input checked="" type="checkbox"/>
							#73
ENGINE Wasp AN I	ENGINE NUMBER (S) 14384/19310 slightly		HOURS FLOWN BY PILOTS				
			INST.	NIGHT	ON TYPE		TOTAL
					SOLO	DUAL	SOLO DUAL
			17	12	42	68	80 100

COMMAND
MONTH
STAGE OF FLIGHT

7
4
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ
5
3RD
5
4

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Aerobatics.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Pupil was taxiing into position for take-off and when broadside to wind, a strong gust lifted port wing and turned a/c onto its nose.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

TN/ANT/was ✓

CLASSIFICATION:

~~57. Miscellaneous.~~

11. Other

11

SECONDARY OR CONTRIBUTORY FACTORS:

~~35. Cross winds and gusts.~~

~~36. Nosing up.~~

ACTION TAKEN:

Nil