

## CASPIR Aircraft Accident Cards

---

**Serial:** 11558

**Title:** Avro Anson Mk. II serial:11558 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 2 aircraft on 1943-December-17. They are: Anson II s/n 11541, Anson II s/n 11558. This accident involved 2 people. Kyle GJ, Murray JM

**Keywords:** RCAFAnson II,11558,19 SFTS,19 Service Flying Training School,Aerodrome,1943-December-17,Kyle,MurrayRCAF L20

**Created:** 1943-12-17

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11558>



PURPOSE OF FLIGHT:

Seq. Armament Exercises No. 4

Seq. 10, 12, 13, 17, 22, 23.

NATURE OF ACCIDENT:

Pilot parked Anson 11558 to do pre take off check and while doing so stbd parking brake failed to hold allowing a/c to move ahead, striking a/c 11541.

TECHNICAL OFFICER'S REPORT:

*M. J. Ten/TS*  
Unserviceable parking brake on Stbd side.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

Remarks of Unit C.O.  
Carelessness on part of pilot, parking too close to other aircraft.

CLASSIFICATION:

~~7. Brake failure.~~

9. Collision *9*

SECONDARY OR CONTRIBUTORY FACTORS:

~~3. Hitting other aircraft.~~

~~24. Carelessness.~~

36 Brake Failure 36

ACTION TAKEN:

Log Book Endorsed.