

## CASPIR Aircraft Accident Cards

---

**Serial:** 7167

**Title:** Avro Anson Mk. II serial:7167 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 2 aircraft on 1944-January-06. They are: Anson II s/n FP789, Anson II s/n 7167. This accident involved 2 people. Ford RM, Leslie LA

**Keywords:** RCAFAnson II,7167,15 SFTS,15 Service Flying Training School,Aerodrome,1944-January-06,Ford,LeslieRCAF L20

**Created:** 1944-01-06

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#7167>

61 ( ) 60 ( ) 59 ( ) 58 ( ) 57 ( ) 56 ( ) 55 ( ) 54 ( ) 53 ( ) 52 ( ) 51 ( ) 50 ( ) 49 ( ) 48 ( ) 47 ( ) 46 ( ) 45 ( ) 44 ( ) 43 ( ) 42 ( ) 41 ( ) 40 ( ) 39 ( ) 38 ( ) 37 ( ) 36 ( ) 35 ( ) 34 ( ) 33 ( ) 32 ( ) 31 ( ) 7 ( )

ACCIDENT CLASSIFICATION

UNIT <b>15 S.F.T.S. Claresholm</b>	COM. <b>4</b>	PLACE <b>M.A.</b>	DATE <b>6-1-44</b>	TIME <b>2040</b>
A/C TYPE <b>ANSON <u>IL</u> ANSON <u>IL</u></b>			H.Q. FILE <b>1300-FP789</b>	
No. <b>FP789 D 7167</b>		CRASH CAT. <b>"D.6" "C.12"</b>	S.E.	M.E. <b>x</b>
			DAY	NIGHT <b>x</b>

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
<b>Leslie, L.A.</b>	<b>AUS LAC</b>	<b>6403</b>	<b>IP</b>	<b>Uninj.</b>	No.	DATE
<b>Ford, R.R.</b>	<b>AUS LAC</b>	<b>436455</b>	<b>PP</b>	<b>Uninj.</b>	<b>A.2</b>	<b>6-1</b>
					D 14 (REVISED)	
					No.	CHECKED
					<b>#4</b>	

MONTH

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
JACOBS LOMB	PT16371/2550 Nil	INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
	ST25494/9864 Nil						
	PT17280/3459 Nil	14	5	24	40		
	ST25252/9622 Nil	13	5	34	27		

STAGE OF FLIGHT

4 ( )  
2 ( )  
1 ( )  
7 ( )  
4 ( )  
2 ( )  
1 ( )  
FORCED LANDING ( )  
TAXIING ( )  
LANDING ( )  
TAKE-OFF ( )  
FLIGHT ( )  
STRATRY ( )  
FATAL ( )  
INJ ( )  
3RD ( )  
5 ( )  
RAF ( )  
M ( )

TYPE OF A/C  
TYPE OF UNIT  
CATEGORY

ACCIDENT CLASSIFICATION

1 ( ) 2 ( ) 3 ( ) 4 ( ) 5 ( ) 6 ( ) 7 ( ) 8 ( ) 9 ( ) 10 ( ) 11 ( ) 12 ( ) 13 ( ) 14 ( ) 15 ( ) 16 ( ) 17 ( ) 18 ( ) 19 ( ) 20 ( ) 21 ( ) 22 ( ) 23 ( ) 24 ( ) 25 ( ) 26 ( ) 27 ( ) 28 ( ) 29 ( ) 30 ( ) 31 ( ) 32 ( ) 33 ( ) 34 ( ) 35 ( ) 36 ( ) 37 ( ) 38 ( ) 39 ( ) 40 ( ) 41 ( ) 42 ( ) 43 ( ) 44 ( ) 45 ( ) 46 ( ) 47 ( ) 48 ( ) 49 ( ) 50 ( ) 51 ( ) 52 ( ) 53 ( ) 54 ( ) 55 ( ) 56 ( ) 57 ( ) 58 ( ) 59 ( ) 60 ( ) 61 ( )

PURPOSE OF FLIGHT:  
Solo practice of night circuits.

TECHNICAL OFFICER'S REPORT:  
Nil

MULT  
TCR/PCM  
TCR/KA

NATURE OF ACCIDENT:

Aircraft 789 moved forward while pilot was doing pre-take-off check and struck aircraft 7167.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:  
FINDINGS: SUMMARY No.

CLASSIFICATION:

~~3. Hitting other aircraft.~~

~~24. Carelessness.~~

9. *Collisions*

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness.~~

~~3. Hitting other a/c.~~

ACTION TAKEN:

Endorsation of log books and grounded for one month.

