

## CASPIR Aircraft Accident Cards

---

**Serial:** 8243

**Title:** Avro Anson Mk. II serial:8243 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1944-January-18. Anson II s/n 8243. This accident involved 1 person. Watson J

**Keywords:** RCAFAnson II,8243,16 SFTS,16 Service Flying Training School,Aerodrome,1944-January-18,WatsonRCAF L20

**Created:** 1944-01-18

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8243>



PURPOSE OF FLIGHT:

Seq. 28 Formation.

TECHNICAL OFFICER'S REPORT:

Nil

*25/1/1951/10/10/10*

NATURE OF ACCIDENT:

Pilot started to take-off. A/C was just airborne when one engine failed to give sufficient revolutions. Pilot cut switches landed and was not able to stop before striking the top of small gulley.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~13. Engine failure.~~

*17*

*17. Forced Landing*

SECONDARY OR CONTRIBUTORY FACTORS:

~~11. Hitting obstructions.~~

ACTION TAKEN:

Nil

*26. Engine trouble - accident*

*26*