

CASPIR Aircraft Accident Cards

Serial: 7609

Title: Avro Anson Mk. II serial:7609 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1944-January-26. Anson II s/n 7609. This accident involved 2 people. Davies TP, Smith V

Keywords: RAFAnson II,7609,34 SFTS,34 Service Flying Training School,Suffield Aerodrome,1944-January-26,Davies,SmithRCAF L20

Created: 1944-01-26

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#7609>

PURPOSE OF FLIGHT:

night cross country.

NATURE OF ACCIDENT:

Successful forced landing, following vibration and loss in revs. of port engine. Pilot unable to return to base on stbd engine, as a/c was losing height rapidly.

CLASSIFICATION:

54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

33. Technical defect.

TECHNICAL OFFICER'S REPORT:

Seizure of #4 piston, port engine, with subsequent failure of cylinder holding down stude.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Nil