

## CASPIR Aircraft Accident Cards

---

**Serial:** 2580

**Title:** North American Harvard Mk.II serial:2580 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1944-January-24. Harvard II s/n 2580. This accident involved 1 person. Van Den Brink ML

**Keywords:** RAFHarvard II,2580,34 SFTS,34 Service Flying Training School,Aerodrome,1944-January-24, Van Den BrinkRCAF L20

**Created:** 1944-01-24

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2580>



PURPOSE OF FLIGHT:

Aerobatics and maximum rate turns.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Pupil had almost completed his landing when a/c swung to the right and ground looped.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

61. Swinging on landing.

SECONDARY OR CONTRIBUTORY FACTORS:

38. Ground loop.

ACTION TAKEN:

Nil