

CASPIR Aircraft Accident Cards

Serial: 2743

Title: North American Harvard Mk.II serial:2743 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1944-January-25. Harvard II s/n 2743. This accident involved 1 person. Samberger A

Keywords: RAFHarvard II,2743,34 SFTS,34 Service Flying Training School,Aerodrome,1944-January-25,SambergerRCAF L20

Created: 1944-01-25

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2743>

122 61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.	DATE 25-1-44		TIME 1455		
			H.Q. FILE 1100-27-43				
A/C TYPE HARVARD II	No. 2743	CRASH CAT. "E" ₁ / ₂	S.E. x	M.E.	DAY x	NIGHT	
			PERSONNEL				
PERSONNEL SAMBERGER, A.		RANK CPL	NUMBER 787806	DUTY PP	INJURIES Uninj.		
TYPE OF A/C		TYPE OF UNIT		MONTH		STAGE OF FLIGHT	
CATEGORY		ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS	
D		Wasp S3HI		4324/8465 Nil		ON TYPE	
C						TOTAL	
B						INST. NIGHT	
A						SOLO DUAL	
						SOLO DUAL	
						102 103 138 159	

COMMAND
MONTH
STAGE OF FLIGHT

4
2
1
7
4
2
1
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ
3RD
INJURY
5
N

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF W N

PURPOSE OF FLIGHT:

Aerobatics and ~~maximum~~ rate turns.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Pupil landed on three points and had almost completed the landing run when the a/c swung to the right, the stbd wing tip touching the ground.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

L S / P >

CLASSIFICATION:

61. Swinging on landing.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil