

CASPIR Aircraft Accident Cards

Serial: FP956

Title: Avro Anson Mk. II serial:FP956 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 2 aircraft on 1944-February-23. They are: Anson II s/n 8244, Anson II s/n FP956. This accident involved 2 people. Bull CR, MacDonald RP

Keywords: RCAFAnson II,FP956,7 SFTS,7 Service Flying Training School,Aerodrome,1944-February-23,Bull,MacDonaldRCAF L20

Created: 1944-02-23

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP956>

PURPOSE OF FLIGHT:

Dual instructions.

TECHNICAL OFFICER'S REPORT: *MUET*

*NIL TCA/PCT
TCA/XA*

NATURE OF ACCIDENT:

Pilot of a/c FP956, taxied out of line and by gross carelessness ran the stbd wing of his a/c through the rudder of a/c 8244 which was parked on the tarmac.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

~~24. Carelessness.~~

9 collisions 9

SECONDARY OR CONTRIBUTORY FACTORS:

~~3. Hitting other a/c.~~

ACTION TAKEN:

Placed on charge and log book endorsed Gross careles.