

ACCIDENT CLASSIFICATION

UNIT	11 S.F.T.S.	COM.	PLACE	DATE	5-2-44	TIME	1145		
	Yorkton			2	M.A.	H.Q. FILE	1100-80-64		
A/C TYPE	CRANE I	No.	8064	CRASH CAT.	"E"1	S.E.	M.E.	DAY	NIGHT
							x	x	
PERSONNEL	RANK	NUMBER	DUTY	INJURIES		SIGNAL			
WALLEY, B.C.	F/O	J21323	FI	Uninj.		No.	DATE		
						No sig.			
						D 14 (REVISED)			
						No.	CHECKED		
						2	<input checked="" type="checkbox"/>		
						#4			
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS						
Jacobs LAMB-1	22004/8198	Nil	INST.	NIGHT	ON TYPE		TOTAL		
	22212/8276	Nil			SOLO	DUAL	SOLO	DUAL	
			71	72	293	93	1075	188	

ACCIDENT CLASSIFICATION

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

7
4
2
1
7
4
2
1
FORCED LANDING
TAKING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ
3RD
5
M

PURPOSE OF FLIGHT:

Refresher training.

TECHNICAL OFFICER'S REPORT:

NIL

NATURE OF ACCIDENT:

Pilot practising forced landing attempted to stretch glide and struck trees on leeward boundary of field.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Disobedience of Standing Orders.

SECONDARY OR CONTRIBUTORY FACTORS:

41. Hitting obstructions.

ACTION TAKEN: