



PURPOSE OF FLIGHT:

Solo night cross country.

Solo night circuits.

NATURE OF ACCIDENT:

Pilot of a/c 8024 returning from night cross country landed without lights - turned off flare path and stopped on taxi path. Pilot of a/c 7697 landed turned off runway colliding with a/c 8024. Had paused for 10 minutes without attempting to taxi in to tarmac, use flashlight or very light to signal tower prior to accident.

TECHNICAL OFFICER'S REPORT:

TCN/FCR/XCA  
NIL/REM/11/11/11/11

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~24. Carelessness.~~

9. Collision

(9)

SECONDARY OR CONTRIBUTORY FACTORS:

~~3. Hitting other a-c.~~

ACTION TAKEN:

Awarded detention and set back one course.