

PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT: Instrument flying. NATURE OF ACCIDENT: Eye witness states: A/C came from COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: westerly direction at about 3 above FINDINGS: SUMMARY No.2272 snow. The wing nearest North shore seemed to be wavering and in an instant CIRCUMSTANCES: A/C flying west was seen a few feet off ice of little lake with stbd wing low. the machine seemed to disappear in a cloud of snow. CAUSE: Unable to maintain equilibrium by sensory means. CONCLUSIONS OF AI.B.: Cause obscure. (1/ The I.O. suggested the following as frobable, cause of the accident. (1) Loss of control. (2) Attempted forced landing. CLASSIFICATION: (3) Unauthorized low flying. He indicated more to the view that for some unknown reason control had been lost and the cras h occurred while attempting to recover. SECONDARY ÖR CONTRIBUTORY FACTORS: NOTE 2 The I.O. was of the opinion that C.A.F.1. Vol. 2 was in use at this Unit rather th. ACTION TAKEN: C.A.P. Y. Vol.2. second edition. . NIL R. C. A. F. L 20 (REVISED) 7M-4-43 (3202) K. P. 5051 H. Q. 885-L 20 C. C. LTD. 7084-43