



PURPOSE OF FLIGHT:

Familiarization of passengers on type.

TECHNICAL OFFICER'S REPORT:

DFM/ACK/PDF/DE/05 NR - 0

NATURE OF ACCIDENT:

Inability of Pilot to maintain height and control of a/c when Port engine failed at app. 400', resulting in unsuccessful forced landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No. 2266

Case of unqualified pilot on type being unable to cope with emergency. NCTE: Investigating Officer found breach of following paras. of C.A.P. 100 Sec. 1, para 430, Sec. 18, para 12, and para 11.

CLASSIFICATION:

~~1. Engine failure in the air.~~

17 Forced Landing

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error.~~

26 Legue Trouble - Accident

ACTION TAKEN: