

CASPIR Aircraft Accident Cards

Serial: 3568

Title: Fleet Fort serial:3568 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 2 aircraft on 1944-February-10. They are: Fleet Fort II s/n 3582, Fleet Fort II s/n 3568. This accident involved 2 people. Jenkins WK, Worgan D

Keywords: RCAF Fleet Fort II, 3568, 3 WS, 3 Wireless School, Stevenson Field
Winnipeg, 1944-February-10, Jenkins, Worgan RCAF L20

Created: 1944-02-10

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000741#3568>

ACCIDENT CLASSIFICATION

TYPE OF A/C	UNIT	3 W.S. Winnipeg	COM.	2	PLACE	Stephenson Field	DATE	10-2-44	TIME	1115	COMMAND
	A/C TYPE	FORT II FORT II	No.	3582 3568	CRASH CAT.	"D" "D"	H.Q. FILE	1100-35-82			
TYPE OF UNIT	PERSONNEL	WORGAN, D.	RANK	P/O	NUMBER	J38382	DUTY	P	INJURIES	Uninj.	SIGNAL
	PERSONNEL	JENKINS, W.K.	RANK	LAC	NUMBER	R257047	DUTY	WO	INJURIES	Uninj.	SIGNAL
CATEGORY	ENGINE	Jacobs L6MB	ENGINE NUMBER (S)	25282/9052 Nil 15719/1904 Nil	INST.	41	NIGHT	23	HOURS FLOWN BY PILOTS		MONTH
	ENGINE	Jacobs L6MB	ENGINE NUMBER (S)	25282/9052 Nil 15719/1904 Nil	INST.	41	NIGHT	23	HOURS FLOWN BY PILOTS		
								ON TYPE		TOTAL	
								SOLO	DUAL	SOLO	DUAL
								63	3	211	150

ACCIDENT CLASSIFICATION

MONTH

STAGE OF FLIGHT

FORCED LANDING

TAXYING

LANDING

TAKE-OFF

FLIGHT

STATRY

FATAL

INJ.

INJURY

#2 CR 2/2

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

MULT

Wireless exercise.

NIL

TRAINING
TCR (X)

NATURE OF ACCIDENT:

Pilot taxiing into parking line,
between two a/c, failed to see park-
ed a/c ahead, and stbd wing hit under-
side of port wing of 3568. Ground crew
man warned pilot too late to avoid collision.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~3. Hitting other a/c.~~

9. Collision

9

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness.~~

ACTION TAKEN:

Log book endorsed "Carelessness".