

TYPE OF A/C		ACCIDENT CLASSIFICATION										COMMAND			
1	2	UNIT	2 W.S.	COM.		PLACE		DATE	26-2-44	TIME	1610	3	4		
		Shepard, Alta.		4	3/4 mi. N. M.A.			H.Q. FILE						7	8
3	4	A/C TYPE	FLEET FORT II	No.		CRASH CAT.	N.A.	S.E.	x	M.E.		DAY	x		
		PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL				9	10	
5	6	Moss, C.H.H.		F/L	C1956	P	Uninj.		No.	DATE		11			12
		Sather, D.M.		LAC	RI15999	Pass	Uninj.		D 14 (REVISED)				13	14	
7	8									No.		CHECKED			
9	10														
11	12														
13	14														
15	16														
17	18														
19	20														
21	22														
23	24														
25	26														
27	28														
29	30														
31	32														
33	34														
35	36														
37	38														
39	40														
41	42														
43	44														
45	46														
47	48														
49	50														
51	52														
53	54														
55	56														
57	58														
59	60														
61	62														

N.A.F.A.

#7.

MONTH

STAGE OF FLIGHT

FORCED LANDING

TAXIING

LANDING

TAKEOFF

FLIGHT

STATRY

FATAL

INJ.

3RD

CURRY

5

2

PURPOSE OF FLIGHT:

Test Flight after major overhaul

TECHNICAL OFFICER'S REPORT:

NIL.

NATURE OF ACCIDENT:

Engine started to miss severely immediately after take-off. Precautionary landing carried out in field.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

13. Engine failure.

SECONDARY OR CONTRIBUTORY FACTORS:

58. Precautionary landings.

ACTION TAKEN: