

CASPIR Aircraft Accident Cards

Serial: FP720

Title: Avro Anson Mk. II serial:FP720 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-March-10. Anson II s/n FP720. This accident involved 1 person. Merrick WT

Keywords: RCAFAnson II,FP720,7 SFTS,7 Service Flying Training School,Aerodrome,1944-March-10,MerrickRCAF L20

Created: 1944-03-10

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP720>

ACCIDENT CLASSIFICATION

UNIT 7 S.F.T.S. MacLeod	COM. 4	PLACE M.A.	DATE 10-3-44	TIME 1105
A/C TYPE ANSON II	NO. FP720	CRASH CAT. "D"1	H.Q. FILE 1300-FP720	
			S.E. x	M.E. x
			DAY x	NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
MERRICK, W.T.	F/O	J16330	PP	Uninj.	NO. A.163	DATE 10-3
					D 14 (REVISED)	
					NO. 2	CHECKED <input checked="" type="checkbox"/>
					#12	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
JACOBS L6MB	25680/15369	Nil					
	9723/25353	Nil					
			13	5	4	10	48
							58

ACCIDENT CLASSIFICATION

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING

TAXIING

LANDING

TAKE OFF

FLIGHT

STAT'RY

FATAL


INJ.

INJURY

3RD

RAF

M



PURPOSE OF FLIGHT:

Practising circuits.

TECHNICAL OFFICER'S REPORT:

NIL

NATURE OF ACCIDENT:

Pilot taxiing to runway after doing take-off check claims that a gust of wind lifted tail in air causing a/c to nose over,

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

35. Cross winds and gusts.

16

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL