

		ACCIDENT CLASSIFICATION																															
TYPE OF A/C	UNIT	9 B&G		COM.	3		PLACE	8 Miles west of Station										DATE	6-3-44		TIME	1505		COMMAND									
		Mont Joli						aerodrome ,										H.Q. FILE															
	A/C TYPE	BATTLE					No.	7463										CRASH CAT.	"C" 14		S.E.	x			M.E.			DAY	x		NIGHT		
TYPE OF UNIT	PERSONNEL		RANK		NUMBER		DUTY		INJURIES		SIGNAL																						

PURPOSE OF FLIGHT:

Scheduled gunnery exercise.

NATURE OF ACCIDENT:

During a scheduled gunnery exercise, a severe glycol leak developed making an immediate forced landing necessary.

TECHNICAL OFFICER'S REPORT: Examination disclosed bad leak in core of glycol rad; allowing large percentage of glycol to escape, resulting in engine overheating and loss of power

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

33. Technical defect.

18

SECONDARY OR CONTRIBUTORY FACTORS:

54. Engine failure in the air.

34. Wheels up landing

ACTION TAKEN: