



PURPOSE OF FLIGHT:

Gunnery exercise.

TECHNICAL OFFICER'S REPORT:

NIL

NATURE OF ACCIDENT:

Pilot attempted to park a/c un-aided by ground crew between two other a/c which had very little space between them. When swinging a/c around into position, tailplane struck frozen snowbank causing sever damage to the tailplane of a/c.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

2 Hitting obstruction.

9

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log book endorsed "Gross Carelessness".