

ACCIDENT CLASSIFICATION

UNIT 3 S.F.T.S. Calgary		COM. 4	PLACE M.A.		DATE 27-3-44	TIME 0825			
A/C TYPE CRANE I CRANE I		No. 7775 D 8691	CRASH CAT. "D"2 "D"		H.Q. FILE 1100-77-75	S.E. X X	M.E. X X	DAY X	NIGHT
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
LINDOE, C.		GB LAC	1523813	PP	Uninj. 27/28		No.	DATE	
MORRIS, K.		AUS LAC	13141	PP	Uninj. 1/29		A.20		27-3
							D 14 (REVISED)		
							No.	CHECKED	
							6		
							#17		
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Jacobs L4MB		21167/4023				ON TYPE		TOTAL	
		21562/442 Nil		INST.	NIGHT	SOLO	DUAL	SOLO	DUAL
		22078/8219 Nil		17	2	32	55	58	102
		22622/8222 Nil		10	-	10	22	38	61

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
TAKING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
3RD
5
M

PURPOSE OF FLIGHT:

Routine flight.

TECHNICAL OFFICER'S REPORT:

NIL

MULL
TCH/PST
TCH/PA

NATURE OF ACCIDENT:

A/C 7775 in attempting to taxi into line misjudged interval between a/c. In turning a/c the tail plane struck the tail plane of a/c 8691.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

3. Hitting other a/c.

9

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Pupil placed on charge for carelessness and action taken promulgated to all T.W. 10 days C.C. Training suspended for one month.