

## CASPIR Aircraft Accident Cards

---

**Serial:** 3613

**Title:** Fleet Fort serial:3613 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1944-March-17. Fleet Fort II s/n 3613. This accident involved 2 people. Harnden SK, Sivewright R

**Keywords:** RCAF Fleet Fort II,3613,3 WS,3 Wireless School,Winnipeg Manitoba,1944-March-17,Harnden,SivewrightRCAF L20

**Created:** 1944-03-17

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000741#3613>



PURPOSE OF FLIGHT:

Practice flight.

TECHNICAL OFFICER'S REPORT:

Nil

7/14/2001

14601

NATURE OF ACCIDENT:

Pilot landed on N-S runway, turned off the right on u/s part of grass area and stopped to raise flaps. On opening throttle with stick back, a/c nosed up. Examination showed there was about 3 inches of snow ~~xxx~~ where wheels rested.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

1. Bad surface of aerodrome.

10

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: