

CASPIR Aircraft Accident Cards

Serial: 11010

Title: Consolidated Canso A serial:11010 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-May-04. Cnso A s/n 11010.

Keywords: RCAF Cnso A,11010,3 OTU,3 Operational Training Unit,,1944-May-04,RCAF L20

Created: 1944-05-04

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000357#11010>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Underside of hull at chine aft of bulkhead 6, port side, badly dented, causing damage to ribs, chine side and bottom plating necessitating extensive metal repair.

NATURE OF ACCIDENT:

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

Damage done to a/c during water handling by some object, possibly a buoy.

Cause of accident obscure. Enquiries among crews who have flown a/c in the three days prior to discovery of damage, have failed to establish either time damage occurred, or crew responsible. A Court of Inquiry is recommended.

CLASSIFICATION:

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: