

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 8 S.F.T.S. Weyburn		COM. 2	PLACE 5 miles W of Trossachs		DATE 23-3-44	TIME 0835		
A/C TYPE HARVARD IIB HARVARD IIB		NO. AJ927D 2896	CRASH CAT. "A" "A"	S.E. X	M.E.	DAY X	NIGHT	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL	
GILLESPIE, W.R.		LAC	R196278	PP	Killed. 927		NO. DATE	
HINTON, R.D.		LAC	R216180	PP	Killed 2896		A.38 23-3	
							D 14 (REVISED)	
							NO. CHECKED	
							8 ✓	
							#50	
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				
Wasp S3HI		213808/11537 totally		INST.	NIGHT	ON TYPE		TOTAL
		213842/11571 "				SOLO	DUAL	SOLO DUAL
				40	20	68	82	106 116
				36	19	50	82	70 115

COMMAND  
MONTH  
STAGE OF FLIGHT

4  
2  
1  
7  
4  
2  
1  
FORCED LANDING  
TAXYING  
LANDING  
TAKE-OFF  
FLIGHT  
STATRY  
FATAL  
INJ.  
INJURY 3RD  
S

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF M 2

TYPE OF A/C  
TYPE OF UNIT  
CATEGORY

PURPOSE OF FLIGHT:

#30 advanced formation cross country.

TECHNICAL OFFICER'S REPORT:

NIL

MULT  
ICR/PSE/F/N  
ICR/AA

NATURE OF ACCIDENT:

A/C AJ927 collided in mid air with a/c 2896 causing both a/c to crash.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No. 2316

CAUSE: Error of LAC Gillespie in (a) failing to wait for a repetition of signal to change from vic to echelon port before commencing to make the change; (b) failing to drop back behind formation while keeping other aircraft of formation in sight to his left before crossing over and flying into his proper position in echelon port; (c) attempting to reach his position in echelon port by passing down under apparently back below other a/c tact in echelon port.

For Recommendations see Summary No. 2316.

CONCLUSIONS OF A.I.B.: Agree. Improper procedure adopted by LAC Gillespie in changing station.

For Notes 1,2,3, See Summary no. 2316

CLASSIFICATION:

26. Collision in the air.

21

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL