

ACCIDENT CLASSIFICATION

UNIT 31 S.F.T.S. Kingston, Ont	COM. 3	PLACE M.A.	DATE 28-3-44	TIME 0920
A/C TYPE HARVARD II HARVARD IIB			H.O. FILE 1300-AJ565	
No. AJ 565D FE 762	CRASH CAT. "D" "B"	S.E. x	M.E.	DAY x
		NIGHT		

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Gladder, I.H. 565 FX	ALA	582043	PP	Uninj.	No.	DATE
Turner, E.A. 762	F/O	149313	FI	Uninj.	054	28-3
Orr, P.J. 762 FX	ALA	112015	PP	Uninj.	D 14 (REVISED)	
					No.	CHECKED
					#65	

MONTH

STAGE OF FLIGHT

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Wasp S3H1	8156/4175 NIL						
Wasp ANI	9826/42/22165						
		24	14	45	42	73	90
		70	110	1308	8	1662	135
		18	16	40	48	62	85

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
INJURY

ACCIDENT CLASSIFICATION

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

TYPE OF A/C

TYPE OF UNIT

CATEGORY

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF

PURPOSE OF FLIGHT:

Training Exercise.

TECHNICAL OFFICER'S REPORT:

NIL

NATURE OF ACCIDENT:

Harvard 11 AJ 565 taxied into Harvard
11 FE 762 (See attached Pilots Report)

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

MULT ✓
TCA/DCI
TCA/XA

CLASSIFICATION:

3. Hitting other aircraft.

9

SECONDARY OR CONTRIBUTORY FACTORS:

24 Carelessness.

ACTION TAKEN:

Awarded 168 hours Detention.