

PURPOSE OF FLIGHT:

Formation flying.

TECHNICAL OFFICER'S REPORT:

NIL

NATURE OF ACCIDENT:

A/C swung into snow bank at landing
damaging port u/c and port wing tip.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

61. Swinging on landing.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log book endorsed "Carelessness" 3 days Orderly
Officer and extra duties.