

ACCIDENT CLASSIFICATION

UNIT 3 S.F.T.S.
Calgary

COM. 4

PLACE Vicinity of Penhold

DATE 25-4-44 TIME 1000

H.Q. FILE 1100-81-45

A/C TYPE CRANE I

NO. 8145

CRASH CAT. "D"2

S.E.

M.E. x

DAY x

NIGHT

PERSONNEL

RANK

NUMBER

DUTY

INJURIES

SIGNAL

FAIRBAIRN, R.D.

F/S R139559

P

Uninj.

No.

DATE

COFFLE, W.J.

NZ LAC 432324

PP

Uninj.

A27

26-4

D 14 (REVISED)

No.

CHECKED

4

#13

ENGINE

ENGINE NUMBER (S)

HOURS FLOWN BY PILOTS

Jacobs L4MB

21625/4457 serious
22572/8161 Nil

INST.

NIGHT

ON TYPE

TOTAL

SOLO

DUAL

SOLO

DUAL

53

154

902

102

937

145

9

3

5

14

26

53

ACCIDENT CLASSIFICATION

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ
3RD
INJURY
5
RAF
M

PURPOSE OF FLIGHT:

Routine cross country.

TECHNICAL OFFICER'S REPORT:

Metal particles found in oil filters.

NATURE OF ACCIDENT:

While on low level cross country flight in the vicinity of Penhold, the port engine failed. The instructor pilot made a single engine landing on the Penhold aerodrome.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

33. Technical defect.

ACTION TAKEN:

NIL