

CASPIR Aircraft Accident Cards

Serial: 2734

Title: North American Harvard Mk.II serial:2734 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1944-April-13. Harvard II s/n 2734. This accident involved 1 person. Lovegrove P

Keywords: RAFHarvard II,2734,34 SFTS,34 Service Flying Training School,Aerodrome,1944-April-13,LovegroveRCAF L20

Created: 1944-04-13

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2734>

ACCIDENT CLASSIFICATION

TYPE OF A/C	UNIT	34 S.F.T.S. Medicine Hat	COM.	4	PLACE	M.A.	DATE	13-4-44	TIME	1030	COMMAND
	A/C TYPE	HARVARD II		NO.	2734	CRASH CAT.	"D"	H.Q. FILE	1100-27-34		
TYPE OF UNIT	PERSONNEL	LOVEGROVE, P.	RANK	LAC	NUMBER	1865295	DUTY	PP	INJURIES	Uninj.	MONTH
	ENGINE	Wasp S3HI	ENGINE NUMBER (S)	213856/11585 Nil		HOURS FLOWN BY PILOTS		ON TYPE		TOTAL	
CATEGORY			INST.	NIGHT	SOLO	DUAL	SOLO	DUAL			STAGE OF FLIGHT
			-	-	30	53	54	86			

ACCIDENT CLASSIFICATION

7
A
2
1
7
4
2
1
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJURY
3RD
S
M
N

PURPOSE OF FLIGHT:

Solo cross country.

TECHNICAL OFFICER'S REPORT:

45/1188/1-10 ✓

NIL

NATURE OF ACCIDENT:

Pupil ground looped on landing in strong cross wind.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~38. Ground loop.~~

2. Swing 2.

SECONDARY OR CONTRIBUTORY FACTORS:

~~35. Cross winds and gusts.~~

ACTION TAKEN:

NIL