

## CASPIR Aircraft Accident Cards

---

**Serial:** FE412

**Title:** North American Harvard Mk. IIB serial:FE412 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1944-April-19. Harvard IIB s/n FE412. This accident involved 1 person. Lumb E

**Keywords:** RAFHarvard IIB,FE412,34 SFTS,34 Service Flying Training School,Aerodrome,1944-April-19,LumbRCAF L20

**Created:** 1944-04-19

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE412>

ACCIDENT CLASSIFICATION

UNIT <b>34 S.F.T.S.</b>	COM. <b>4</b>	PLACE <b>M.A.</b>	DATE <b>16-4-44</b>	TIME <b>1830</b>
Medicine Hat			H.Q. FILE <b>130-FE412</b>	
A/C TYPE <b>HARVARD IIB</b>	NO. <b>FE412</b>	CRASH CAT. <b>"E"</b>	S.E. <b>x</b>	M.E. <b>x</b>
			DAY <b>x</b>	NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
<b>LUMB, E.</b>	<b>LAC</b>	<b>1458903</b>	<b>PP</b>	<b>Uninj.</b>	No. <b>No sig</b>	DATE
					D 14 (REVISED)	
					No. <b>30</b>	CHECKED
					<b>#108</b>	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
<b>Wasp S3HI</b>	<b>262293/13128 Nil</b>	-	-	<b>7</b>	<b>15</b>	<b>41</b>	<b>60</b>

TYPE OF A/C	TYPE OF UNIT	CATEGORY	COMMAND	MONTH	STAGE OF FLIGHT	7
						4
						2
						1
						7
						4
						2
						1
						FORCED LANDING
						TAXIING
						LANDING
						TAKE-OFF
						FLIGHT
						STAT'RY
						FATAL
						INJ.
						3RD
						5
						RAF
						M.A.

ACCIDENT CLASSIFICATION

