

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 1 O.T.U. Bagotville	COM. E	PLACE 1 mile S of Arvida	DATE 22-4-44	TIME 1510 GMT
A/C TYPE HURRICANE XIIA		NO. BW848	H.Q. FILE 1300-BW848	
		CRASH CAT. "D"	S.E. x	M.E. x
			DAY x	NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
PATERSON, G.	SGT	R190893	P	Uninj.	NO. A365	DATE 22-4
					D 14 (REVISED)	
					NO. 11	CHECKED <input checked="" type="checkbox"/>
					#16	

MONTH

STAGE OF FLIGHT

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS						
		ON TYPE		TOTAL				
Backard Merlin	19279/A524	Unknown	INST.	NIGHT	SOLO	DUAL	SOLO	DUAL
			30	19	19	-	128	131

FORCED LANDING
TAKING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
3rd
S

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF MZ

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Low flying below 300' and aerobatics above 8000'

FB/ADP/ES/NK/IZ/00016

CAUSE OF E/A OBSCURE

NATURE OF ACCIDENT:

Engine failed in the air, pilot made forced landing wheels up, damaging wing tip, aileron and propellor.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~54. Engine failure in the air.~~

17

17 Forced Landing

SECONDARY OR CONTRIBUTORY FACTORS:

~~34. Wheels up landing.~~

ACTION TAKEN:

26 Engine trouble - Accident

NIL