

CASPIR Aircraft Accident Cards

Serial: 3616

Title: Fleet Fort serial:3616 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-April-17. Fleet Fort II s/n 3616. This accident involved 2 people. Snider AL, Syrett JH

Keywords: RCAF Fleet Fort II, 3616, 3 WS, 3 Wireless School, Stevenson Field
Winnipeg, 1944-April-17, Snider, Syrett RCAF L20

Created: 1944-04-17

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000741#3616>

61 () 60 () 59 () 58 () 57 () 56 () 55 () 54 () 53 () 52 () 51 () 50 () 49 () 48 () 47 () 46 () 45 () 44 () 43 () 42 () 41 () 40 () 39 () 38 () 37 () 36 () 35 () 34 () 33 () 32 ()

ACCIDENT CLASSIFICATION

UNIT 3 W.S. Winnipeg		COM. 2	PLACE Stevenson Field		DATE 17-4-44	TIME 2000			
A/C TYPE FORT II		NO. 3616	CRASH CAT. "C"		H.Q. FILE 1100-36-16				
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
SYRETT, J.H.		P/O	J38934	P	Uninj.		NO. A86	DATE 19-4	
SNIDER, A.L.		LAC	K214387	WO	Uninj.		D 14 (REVISED)		
							NO. 3	CHECKED <input checked="" type="checkbox"/>	
							#3		
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Jacobs L6MB		15349/25660 Nil				ON TYPE		TOTAL	
				INST.	NIGHT	SOLO	DUAL	SOLO	DUAL
				43	9	74	3	184	132

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

7 ()
4 ()
2 ()
1 ()
7 ()
4 ()
2 ()
1 ()
FORCED LANDING ()
TAXIING ()
LANDING ()
TAKE-OFF ()
FLIGHT ()
STAT'RY ()
FATAL ()
INJURY ()
3RD ()
5 ()
RAF ()
M ()

ACCIDENT CLASSIFICATION

1 () 2 () 3 () 4 () 5 () 6 () 7 () 8 () 9 () 10 () 11 () 12 () 13 () 14 () 15 () 16 () 17 () 18 () 19 () 20 () 21 () 22 () 23 () 24 () 25 () 26 () 27 () 28 () 29 () 30 ()

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT: 25/152/035

Wireless school.

NATURE OF ACCIDENT:

NIL

A/C swung to right after touching down three points. Pilot tried to correct with full rudder and throttle, but a/c did not respond, and continued swing which developed into ground loop. Both front oleo legs buckled and a/c settled onto ground.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~38. Ground loop.~~

2. ~~2.~~ 2. Swung

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL